

Under Review Notification

Raised By: Arkam Kindeel

Product #: D139-799-029

Date: 14.01.21

Product Name: Fuel Cap Hinge

Part Number	Drawing/Document	"Y" or "N" Required								Instructions
		HOLD SHIPMENT	Red Tag/Quarantine Stock	Advise customers	Stop Production	Re-Work Stock	IPP Under Review	Blue File Under Review	ECN # Required	
D4722-1	D4722 Rev. B	Y	Y	N	Y	N	Y	Y	510	Part design revised
D4722-3	D4722 Rev. B	Y	Y	N	Y	N	Y	Y	510	Part design revised
D4722-041	D4722 Rev. B	Y	Y	N	Y	N	Y	Y	510	Assembly design revised
D139-799-029	IIN-D139-799 Rev. H	Y	Y	N	Y	N	Y	Y	510	D139-799-029 Hinged Fuel Cap Kit revised.

Description of issue:

D4722-041 hinge interferes with aircraft door. Parts redesigned to avoid interference.
IIN-D139-799 Rev. H revised to Rev. I

Distribution:

General Manager
Production Manager
Director Quality Assurance
Design Manager

Chief Engineer
Engineering Project Managers
Engineering Clerk
Marketing